

Deposition path strategies - Wire and Arc Additive Manufacturing (WAAM) for steel – Gaz Metal Arc Welding (GMAW)


1. Errors in the start and stop points

- Open contour


ZIG

ZIG-ZAG



VS



- Closed contour




◆ - start/stop point



Rule of thumb

- Open contours: change deposition direction from layer to layer
- Closed contours: rotate start point as within the layer as between the layers



2. Determine step over value




Step over value depend on ratio of wire feed speed (WFS) to travel speed (TS):

- If $WFS/TS > 12.5$ then $d = \frac{1}{2h} (2R^2 \arcsin \frac{w}{2R} + wh - wR)$
where $R = \frac{(h^2 + w^2/4)}{2h}$
- If $WFS/TS < 12.5$ then $d = \frac{2w}{3}$

4. Inclined walls




$$h_a \approx h \cos \alpha$$




Rule of thumb

- If $\alpha < 45^\circ$: print in PA position
- If $\alpha \geq 45^\circ$: print in PB position.
- Rotate the table when $\alpha > 60^\circ$ due to humps formation and gravity issues
- Use special strategy to overcome acute angles




3. Main strategies for solid components



Rule of thumb

- Add 1-2 contour passes when using zig or zig-zag strategy to eliminate stairs effect

5. Crosses



Rule of thumb

- $L = 0.5w$, crater filling time 0.5 sec
- Print tails first, after print base and contours